

Changed out all the parts that were leaking.
Pressure switch and gauge were not accurate,
and there was no relief valve.
This was about to crack.
replaced with a bronze
fitting.



New pressure switch, valve, gauge, and shut-off on the right side.
Raised tank so the pipes go straight into the tee.


Pump
Pump
This was pretty bad.


We made it safer.



Then I went overboard.



And kept swimming.


Cleaned up.


Sad little straw
by the river.


Strong like bull
pipeline for the
people.


From this...


...to this...


...and this.




From this...


...to this